Date:

Wednesday, 11/30/2005 8:10:29 AM

User:

Linda Lacelle

**Process Sheet** 

Customer **Job Number**  : CU-DAR001 Dart Helicopters Services

: 25024

**Estimate Number** P.O. Number

: 10407

This Issue

Prsht Rev.

First Issue

:N/A : 11/30/2005

: NC

: WIA : 25024

S.O. No. : N/A

: MACHINED PARTS

**Part Number Drawing Number** 

**Drawing Name** 

: D3173041 : D3173 REV B

: BEAM ASSEMBLY

**Project Number** 

: N/A : B

:NIA

: 12/7/2005

**Drawing Revision** Material

**Due Date** 

Qty:

4 Um:

Each

**Previous Run** Written By

Checked & Approved By

Comment

:See Commen

: Est. A 02.12.05 New issue KJ/RF

**Additional Product** 

Job Number:



Seq. #:

**Machine Or Operation:** 

Description:

1.0

M6061T6TR40X20W125

6061-T6 Rect Tube W.125



Comment: Qty.:

4.9219 f(s)/Unit Total: 19.6875 f(s)

6061-T6 Rect Tube W.125

Material: 6061-T6 (QQ-A-200/8) Rect. Tube 4" x 2" x 0.125 thick

(M6061T6TR4.0x2.0W125)

Batch M19265

oslialio

2.0

BAND SAW

BAND SAW



Comment: BAND SAW

Cut blank: 56" long

Machine holes as per Folio FA295 and Dwg D3173

Identify as D3173-1

Oslialio

3.0

HAAS1

HAAS CNC VERTICAL MACHINING #1





Comment: HAAS CNC VERTICAL MACHINING #1

Machine holes as per Folio FA295 and Dwg D3173Identify as D3173-1

Ml

4.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE



Comment: INSPECT PARTS AS THEY COME OFF MACHINE



SECOND CHECK

5.0

QC8



Comment: SECOND CHECK

Daté: \* Wednesday, 11/30/2005 8:10:30 AM Linda Lacelle User: **Process Sheet** Drawing Name: BEAM ASSEMBLY Customer: CU-DAR001 Dart Helicopters Services Part Number: D3173041 Job Number: 25024 Job Number: #F **Description:** Seq. #: **Machine Or Operation:** SMALL & MEDIUM FAB RESOURCE 1 SMALL FAB 1 6.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 Deburr SECOND CHECK **@6**8 7.0 QC5 Z Comment: SECOND CHECK SMALL & MEDIUM FAB RESOURCE 1 8.0 SMALL FAB 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 Drill Ø0.316" holes as per Dwg D3173 C'sink holes as per Dwg D3173 INSPECT WORK TO CURRENT STEP 9.0 QC5 Comment: INSPECT WORK TO CURRENT STEP HAND FINISHING RESOURCE #1 10.0 HAND FINISHING1 Comment: HAND FINISHING RESOURCE #1 05.12.14 Chemical Conversion Coat as per QSI 005 4.1 Nut Plate D3178041 11.0 2.0000 Each(s)/Unit Total: 8.0000 Each(s) Comment: Qty.: **Nut Plate** Pick K10017. Install Nut Plate as per Dwg D3173. D3178-041 is included in K10017 BOM. Pick: Part Number Description Batch Qty 05/12/15 D3178-041 **Nut Plate** 12.0 MS20601AD4W4 8.0000 Each(s)/Unit Total: 32.0000 Each(s) Comment: Qty.: Rivet Pick: Description Qty Part Number 8 MS20601AD4W4 Rivet

Date: \* Wednesday, 11/30/2005 8:10:30 AM Linda Lacelle User: **Process Sheet Drawing Name: BEAM ASSEMBLY** Customer: CU-DAR001 Dart Helicopters Services Part Number: D3173041 Job Number: 25024 Job Number: Description: Seq. #: **Machine Or Operation:** INSPECT WORK TO CURRENT STEP 13.0 QC5 Comment: INSPECT WORK TO CURRENT STEP POWDER COATING POWDER COATING 14.0 Comment: POWDER COATING Powder Coat Gloss White (Ref: 4.3.5.1) per QSI 005 4.3 05 12 19 Ensure Nut Plate thread is covered. INSPECT POWDER COAT/CHEMICAL CONVERSION 15.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION Mounting Lug 16.0 D3175041 Comment: Qty.: 2.0000 Each(s)/Unit Total: 8.0000 Each(s) Mounting Lug Assemble per Dwg D3173. Install Mounting Lug as per Dwg D3173. D3175-041 is included in K10017 BOM. Pick: Description Batch Qty Part Number FF 05/12/20 2 D3175-041 Mtg Lug 17.0 AN35A 32.0000 Each(s) Comment: Qty.: 8.0000 Each(s)/Unit Total: **Bolt** Pick: Part Number Description Batch Qty M15205 AN3-5A Bolt 05/12/20 Bolt 18.0 AN523A Comment: Qty.: 8.0000 Each(s) 2.0000 Each(s)/Unit Total: **Bolt** Pick: Description Qty Part Number FF 05/12/20 AN5-23A **Bolt** 

Date: Wednesday, 11/30/2005 8:10:30 AM User: Linda Lacelle **Process Sheet Drawing Name: BEAM ASSEMBLY** Customer: CU-DAR001 Dart Helicopters Services Part Number: D3173041 Job Number: 25024 Job Number: Seq. #: Description: **Machine Or Operation:** AN960JD10 Washer 19.0 Comment: Qty.: 32.0000 Each(s) 8.0000 Each(s)/Unit Total: Washer Pick: Description Qty Part Number FF 05/12/20 M16066 Washer AN960JD10 AN960JD516 20.0 Comment: Qty.: Total: 16.0000 Each(s) 4.0000 Each(s)/Unit Washer Pick: Description Qty Part Number 05/12/20 AN960JD516 Washer MS21042L5 21.0 8.0000 Each(s) Comment: Qtv.: 2.0000 Each(s)/Unit Total: Nut Pick: Qty Part Number Description 05/12/20 2 MS21042L5 SMALL FAB 1 22.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 Assemble per Dwg D3173. Install Mounting Lug as per Dwg D3173. D3175-041 is included in K10017 BOM. INSPECT WORK TO CURRENT STEP 23.0 QC5 Comment: INSPECT WORK TO CURRENT STEP 24.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 // 55/h/2 Identify as D3173-041 and Pack with D130-701-041 Location: 7

Page 4

Form: rprocess

Date: User: Wednesday, 11/30/2005 8:10:30 AM

Linda Lacelle

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BEAM ASSEMBLY

Job Number: 25024

Part Number: D3173041

Job Number:



Seq. #:

**Machine Or Operation:** 

Inspection Level 21

Description:

25.0

DC

DOCUMENT CONTROL



Comment: DOCUMENT CONTROL



Job Completion





D3065-5DART AEROSPACE LTD	Work Order:	
Description: Beam	Part Number:	D3173-1
Inspection Dwg: D3173 Rev: B		Page 1 of 1

## FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

	<u></u>					·
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
56.00	+/-0.030	56.00	~			
23.629	+/-0.010	23.630	/			
15.33	+/-0.030	15.33	<b>₩</b>			
2.00	+/-0.030	2.0	<u></u>			
4.00	+/-0.030	4.00	~			
0.500	+/-0.010	,500				
1.720	+/-0.005	1.720				
1.000	+/-0.005	1.000	<u></u>			
0.860	+/-0.005	. 860				
Ø0.203	+0.005/-0.000	,203				
Ø0.129	+0.005/-0.000	Ø.129	~			
		-				
\						

Measured by:	Audited by:	Prototype Approval:	N/A
Date: 05/12/10	Date: 05/12/10	Date:	N/A

Rev	Date	Change		Revised by	Approved
Α	04.02.25	New Issue	P/O D3173-041	KJ/RF	





	DESIGI	OP	DRAWN BY	DART AEROSPACE LT HAWKESBURY, ONTARIO, CANADA	D
١	CHECK	(ED,	APPROVED	DRAWING NO.	REV. B
1		#	-#	D3173 shi	EET 1 OF 3
1	DATE		<u> </u>	TITLE	SCALE
	03.0	1.07		BEAM ASSEMBLY	NTS
	Α		02.12.03	NEW ISSUE	
	В		03.01.07	REMOVE PIP PINS	

## **PARTS LIST**

QTY	PART NUMBER	DESCRIPTION
Х	D3173-041	BEAM ASSEMBLY
1	D3173-1	BEAM
2	D3175-041	MOUNTING LUG
2	D3178-041	NUT PLATE
8	AN960JD10	WASHER
4	AN960JD516	WASHER
2	MS21042L5	NUT
8	MS20601AD4W4	RIVET
8	AN3-5A	BOLT
2	AN5-23A	BOLT


## **NOTES**


## D3173-1 BEAM:

- 1) PART IS SYMMETRICAL ABOUT CENTERLINE
- 2) MATERIAL: 6061-T6 RECTANGULAR TUBING, 4" x 2" x 0.125" WALL (QQ-A-200/8) (REF DART SPEC. M6061T6TR4.0x2.0W125
- 3) BREAK ALL SHARP EDGES 0.010-0.020
- 4) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1 POWDER COAT WHITE (4.3.5.1) PER DART QSI 005 4.3 OUTSIDE ONLY
- 5) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 6) ALL DIMENSIONS ARE IN INCHES









Copyright © 2002 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

